

Innovative Revivor Supreme Service

\$30.00 a Ball

One year Maintenance Service Program

3 Services for \$70.00, over 22% Savings

I keep the records for you!



With this service, will run your bowling ball through the Revivor, thoroughly clean the bowling ball, take the surface back to factory finish!

Bring Your Ball Back To Life!!

Is your bowling ball not hooking anymore?!

Over time your resin or particle bowling will absorb oil as it rolls down the lane. The absorption of this oil is what makes the ball hook and create friction. As the oil fills the pores of the ball the friction will decrease and you lose ball reaction on the lane. Two hours in the new Revivor Oven will safely remove all the oil from your bowling ball. Combine this with a resurface and your ball will perform as it did the day you took it out of the box!

“Innovative Bowling Products Revivor Oven revives bowling ball to maximum performance. Consistent heat draws the oil from the bowling balls. Forced air circulates the heat evenly. Electronic controller assures constant temperature. Balls continually rotate during the process. Absorbent pads collect the oil as the balls turn. 8 years of field testing has never harmed a ball. Innovative has designed this unit for the sole purpose of extracting oil from reactive and proactive bowling ball cover stocks. Drawing out the oil by the use of thermal reaction is a proven method of bringing back the original characteristics of the ball. The Revivor removes the oil with an even, digitally controlled heat pattern so as not to damage the bowling ball. Balls should have the oil extracted approximately every 40 to 50 games, depending on the lane conditions and the level of performance each bowler wishes to maintain.”

